

PATROLLING DISTRIBUTION SYSTEM			
Patrol Starting Date	11-21-12	Patrol Ending Date	11-21-12
Mapping Section	Magnolia Rd Creeks	Crossing. Block Map Section	
VISUAL OBSERVATION INSPECTION			
Leakage Indicated (location and indication: vegetation, asphalt, concrete, excavation, erosion, tampering, damage)			
2" Creek crossing exposed on Magnolia St. No obvious sign of leaks from the line. The crossing is protected with steel casing pipe.			
Condition at highway, major thoroughfare, secondary road, railroad crossings, right-of-ways.			
Other extenuating circumstances that may affect the present and continued safety and integrity of the pipeline facility.			
Follow-up maintenances, repairs, preventative measures, testing, and precautionary actions.			
Through leak survey complete in the area of exposure.			
Atmospheric corrosion survey, involving localized and general corrosion. Corrosion at the riser where it exits the ground. Checks for the effects of lightening and stray current as well chemical/bacteria electrolytes.			
Number of qualified employees patrolling ? (1-10)		1	
Signature Patrolling Personnel	Jason Warner	Date of This Report	11-21-12
Signature Patrolling Personnel		Date of This Report	
Signature Patrolling Personnel		Date of This Report	
Signature Patrolling Personnel		Date of This Report	